

0239Z 01 NOV 64

SECRET

DIRECTOR

25X1A

ROUTINE

TOR: 0257Z 01 NOV 64

IN 55405

ops 7-8

[REDACTED]

INFO

[REDACTED]

CHE

[REDACTED]

5917

25X1A
25X1A
25X1A
25X1A

[REDACTED] S

A. 0224C

B. 352

C. [REDACTED] 25X1A

25X1A

D. HQ DIRECTED, [REDACTED] 3, 26, 8, 30, 33, 34

E. 1. COCKPIT AUTO HEAT CONTROL WILL NOT HOLD A WARM TEMPERATURE.

2. SYSTEM XIII PRESSURIZATION VALVE CLOSE LIGHT (AMBER) DID NOT ILLUMINATE WHEN SELECTOR SWITCH WAS PLACED IN CLOSED POSITION.

END OF MESSAGE